

# Laser<sup>®</sup> FE Replenisher

Laser FE Replenisher is a concentrated acidic fluoride solution used to replenish the Laser FE working bath. Please refer to the Laser FE product bulletin for complete details on operating conditions and instructions for the Laser FE process.

## Features & Benefits

Highly Concentrate	Smaller Storage footprint
Stable	Five-year shelf life

## Operating Conditions

Laser FE Replenisher is a concentrated acidic fluoride solution used to replenish the Laser FE working bath. Please refer to the Laser FE product bulletin for complete details on operating conditions and instructions for the Laser FE process.

## Waste Disposal

Discharge to a disposal system. In order to be completely informed on the latest regulations for your area, please contact the local authorities.

## Caution

**DO NOT STORE USED LASER SOLUTIONS IN SEALED DRUMS. DISCHARGE USED LASER SOLUTIONS TO WASTE TREATMENT SYSTEMS EQUIPPED TO HANDLE THEM.**

Laser FE Replenisher is an acid fluoride solution. Avoid contact with skin and eyes. Wear protective clothing, goggles, and rubber gloves. Flush exposed areas immediately with clean, cold water. In case of injury, contact a doctor immediately.



**Cleaning**  
the Hard to Clean



**Finishing**  
the Hard to Finish



**Treating**  
the Hard to Treat

WARRANTY: THE QUALITY OF THIS PRODUCT IS GUARANTEED ON SHIPMENT FROM OUR PLANT. IF THE USE RECOMMENDATIONS ARE FOLLOWED, DESIRED RESULTS WILL BE OBTAINED. SINCE THE USE OF OUR PRODUCTS IS BEYOND OUR CONTROL, NO GUARANTEE EXPRESSED OR IMPLIED IS MADE AS TO THE EFFECTS OF SUCH USE, OR THE RESULTS TO BE OBTAINED.

---

## **Our people. Your problem solvers.**

For more information on this process please call us at

1-800-648-3412

or [techservice@hubbardhall.com](mailto:techservice@hubbardhall.com)

